


TECHNICAL SERVICE BULLETIN 1436**TO: ALL GRAVELLY OUTLETS – U. S. & CANADIAN****DATE: NOVEMBER 2, 1972****SUBJECT: 44" POWER BRUSH – NUMBER 19242E1**

On all 19242E1 Power Brushes shipped from our factory prior to October 30th, 1972, one extra spacer, part number 19320P1, has been assembled.

If you received a 19242E1 Power Brush before the above date, please remove the 19320P1 spacer on the right hand side of the brush shaft. (Right hand side when viewed from operator's position.)

The spacer can cause binding in the brush operation if not removed.

It appears as item 62 on the brush illustrated parts list number 19669P1.



M. H. Lance, Manager
Customer Service Department

MHL/bh