

GRAVELY *Technical* **BULLETIN**



BULLETIN NO. 934

DATE: January 19, 1962

TO: ALL OUTLETS

SUBJECT: Change in Adjusting Bracket for Rotary Plow and Rotary Cultivator: New position for assembly of Bracket on Rotary Plow.

The 5307 Cast Bracket will no longer be supplied for the Rotary Cultivator.

The new style A-301 now being used on production of the Rotary Plow has a longer slot to allow the Plow Drive to be set at a perpendicular position for the Rotary Cultivator, as well as setting the Plow Drive for any positions previously available.

All Rotary Cultivator Drives will be shipped with the A-301, A-302 assembly.

The new style A-301 will be supplied on Special Order, no charge, for Rotary Cultivators to be sold to customers having the old style A-301 on his plow, or any Plow Drives you have in stock that will be sold for use with a Rotary Cultivator.

CHANGE IN POSITION

To effect the perpendicular mounting, it is necessary to mount the A-301 in a new position. It is shown in the accompanying photograph.

